



Prüfbericht - Nr.:21172578.001

Test Report No.:

Seite 1 von 21

Page 1 of 21

Client (Customer no. and address): Auftraggeber (Kunden-Nr. u. Adresse):		Jiangyin Hareon Power Co., Ltd. No. 178 Huanzhen North Road, Huangtang Industrial Zone, Xuxiake Town Jiangyin Jiangsu, 214407 P.R. China			
Test item: Gegenstand der Prüfung:	Photovoltaic (PV) Module(s)	Date of receipt: Eingangsdatum:	04 May 2011		
Module type designation: Modultypen-Bezeichnung:	HR-xxxP-18/Bb	xxx=200-245, increment of 5			
Order no.: Auftragsnummer:	21216844	Quotation no.: Angebotsnummer:	-		
Testing location: Prüfart:	Solar Energy Assessment Center Cologne TÜV Rheinland Energie und Umwelt GmbH Am Grauen Stein, 51105 Köln, Germany Tel.: ++49-221/806-2477, Fax: ++49-221/806-1350				
Test specification: Prüfgrundlage:	2 PFG 1917/05.11 (is equivalent to IEC 62716 darf C) "Ammonia corrosion testing of photovoltaic (PV) modules"				
Test result: Prüfergebnis:	All of the required tests were passed according to the pass criteria outlined in the test specification noted above. It is therefore declared, that the PV modules of the aforementioned type fulfil the requirements and it is recommended that certification should be granted.				
compiled by / erstellt:		reviewed by / kontrolliert:			
					
08 August 2011	Dipl.-Ing. S. Menzler	08 August 2011	Dipl.-Ing. W. Vaalßen		
Date Datum	Title/Name Titel/Name	Date Datum	Title/Name Titel/Name		
Sonstige Aspekte / other aspects:					
Abkürzungen:	P(ass) F(ail) N/A N/T	= entspricht Prüfgrundlage = entspricht nicht Prüfgrundlage = nicht anwendbar = nicht getestet	Abbreviations:	P(ass) F(ail) N/A N/T	= passed = failed = not applicable = not tested
This test report relates to the listed test samples. Without permission of the test centre this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products.					
Dieser Prüfbericht bezieht sich nur auf die gelisteten Prüfmuster und darf ohne Genehmigung der Prüfstelle nicht auszugsweise vervielfältigt werden. Dieser Bericht berechtigt nicht zur Verwendung eines Prüfzeichens.					

Prüfbericht - Nr.: 21172578.001
Test Report No.:

Seite 2 von 21
Page 2 of 21

Address/es of the manufacturing site/s:

Name / Description:	Jiangyin Hareon Power Co., Ltd.
Street:	No. 178 Huanzhen North Road, Huangtang Industrial Zone, Xuxiake Town,
Postcode / City:	214407 Jiangyin, Jiangsu.
Country:	P. R. China
Type of production:	C-Si PV module production
Inspection report no:	15036571.002

Name / Description:	Jiangyin Xinhui Solar Energy Co., Ltd.
Street:	No. 15, Xinyang Road, Xinqiao Town,
Postcode / City:	214426 Jiangyin City, Jiangsu
Country:	P. R. China
Type of production:	C-Si PV module production
Inspection report no:	15042428.001